

INSPECTORATE

QUALITY CERTIFICATE

Vessel Customer Operation "Hatteras" Sprague Energy Analysis Port Date Terminal New Bedford, MA January 18, 2007 Sprague New Bedford

Report Reference 014307

Sample # 1131823

Name of material being tested Description of sample source Samples Drawn by (company) Samples Tested by (company)

1.0% No 6 Fuel Oil

Shore Tank 3 After Discharge Inspectorate Inspectorate

Tests being Performed	Test method	Sample Results	
Gravity API @ 60F / Density Flash Point, PMCC, F Viscosity cSt @ 122F Viscosity SSF @ 122F Pour Point C / F Sulfur , Wt% Water and Sediment, Vol % Sediment by Extraction, wt% Water by Distillation, Vol% Gross Heat of Combustion, BTU / Ib Gross Heat of Combustion, BTU / gal Ash, wt % Vanadium, ppm Sodium, ppm Nitrogen, wt% Ashphaltenes, wt% Conradson Carbon Residue Aluminum, ppm Silicon, ppm	D - 4052 D - 93 D - 445 D - 2161 D - 97 D - 4294 D - 1796 D - 473 D - 95 D - 240 D - 240 D - 482 D - 5863B D - 5863B D - 5762 IP - 143 D - 189 D - 5814	11.3 / 212 356.6 168.3 -3/27 0.849 0.02 0.10 <0.1 18,411 151,935 0.05 40 16 0.36 4.07 10.42 40 91	0.9906
SPRAGUE PROVIDES THE ATTACHED INSPECTION REPORT/ANALYSIS REPRESENTING THE SPECIFICATIONS OF THE PRODUCT AT THE SPRAGUE TERMINAL IN TANK ON THE DATE OF INSPECTION NOTED ON THE CERTIFICATE, THIS ANALYSIS IS PROVIDED TO THE CUSTOMER FOR THE PURPOSE OF ESTABLISHING THE INDEPENDENTLY VERIFIED PRODUCT SPECIFICATION ON A COMPOSITE BASIS IN SPRAGUE'S TERMINAL SHORE TANK AS NOTED ON THE CERTIFICATE. THE INSPECTION REPORT IS NOT TO BE USED FOR ANY OTHER PURPOSE SPRAGUE DISCLAIMS ANY LABLITY FOR THE PRODUCT AFTER DELIVE BY SPRAGUE TO CUSTOMER. SPRAGUE DISCLAIMS ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR AN INTENDED USE EXCEPT AS MAY BE SPECIFICAL SET FORTH IN WRITING IN ANY CONTRACT OR TERMS OF SALE BETWEEN SPRAGUEND A BUYER OF PRODUCT. SPRAGUE ASSUMES NO LIABILITY FOR CLAIMS OR LOSS THAT MAY ARISE FROM CUSTOMER'S USE OF THIS INSPECTION REPORT/ANALYSIS.	LLY LLY		

^{**} Annotates Analysis Contracted Out

Michael White 6

^{***} Annotates Loadport information- this test was not performed by Inspectorate